

The slide features two large, abstract green geometric shapes. On the left is a tall, narrow triangle pointing downwards. On the right is a larger, more complex shape composed of several overlapping triangles and polygons in various shades of green, creating a layered effect. The main title is centered between these two shapes.

Board Walk Around

April 7, 2018

Charlie Unbehaun, Ken Ross, Steve Nesmith, Carol Parent, Dave Vandermark,
Steve Reed, Tim Gibelyov, Earl Austin, Stuart Berry, Mark Smokowicz



Fence sagging



Correct Height of backers



Skips at 25yds on pistol range



Trees growing out of berm



Neighbor structures in sight



Damaged section of Creek Cover



Damaged sections of Creek Cover



Sample of new creek cover section





Barn doors planned 100 yd Rifle



Safety Line on 100 yd Rifle faded



Firing Line on 100 yd Rifle faded



25 yd Rifle targets at rifle range



50 yd rifle target stands/berm



Concession stand repair or replace



Target stand on extended Rifle Range



Turkey Shoot Area



No Signs



Fence down



3-Wheeler tracks onto property



Missing fence





Archery Range



Needs a bench



Archery roof



Archery roof





Sink hole under bench




Trash behind grill



Trap house steps





Gazebo electrical outlet not working



Sign over vestibule?

Board Walk Around		
7-Apr-18		
	Area Needs Attention	Possible Solution
<u>Pistol House</u>		
	Sagging Fence on walkway over creek	Reset posts
	Skips at 25 yd marker	Bales of hay across 25 yd marker
<u>Action Bays</u>		
	Trees growing in berm	cut back, leave roots
	Neighbors structures in view	plant trees
<u>Warner-Koch Drain</u>		
	Creek Cover sections damaged	replace creek cover
<u>Trap House</u>		
	trip hazard, loose block	reset block or remove
<u>Rifle Range</u>		
	100 yd Safety Line faded	repaint
	100 yd Firing Line faded	repaint
	25 yd target stand wobbly	replace with post hole sleeves
	Open window on 100yd	install rolling barn doors
	ext range, gap on overhead berm structure	inspect, fill gap
<u>Archery Range</u>		
	missing bench	add picnic bench
	Whole in roof	repair roof with metal structure
<u>South West side of Property North of the Creek</u>		
	missing fence	install fence
	missing signs	add signs
<u>Grill Area</u>		
	Sink hole forming by tanks	
	trash behind grill	dispose of
<u>Gazebo</u>		
	electrical outlet non functional	repair
<u>Clubhouse</u>		
	water leaking between bar and storage	seal
	chimney flue damage	repair/reline

